

From: Sgraves@TechLawInc.com
Sent: 2/11/2012 11:02:09 AM
To: "Richard Fetzer" <Fetzer.Richard@epamail.epa.gov>; "Richard Rupert" <Rupert.Richard@epamail.epa.gov>
CC:
Subject: Dimock - HW-16 - Sediment Filter

Rich,

I was informed yesterday evening that during the sampling of HW-16 on the morning of 2/10/12, Brent the engineer from SRL, who operates the residential Cabot Treatment Systems removed a sediment filter prior to sampling. The sediment filter was not replaced, as it was only noticed by START after Brent had left to demobe back home. The START Sampling Team Leader said that there is a tech who stays in the area. I thought you may want to contact Cabot and inform them so they can have the tech re-install the sediment filter.

Thanks,

Suddha Graves
TechLaw, Inc.
2208 Warwood Ave
Wheeling, WV 26003
304-230-1230 (office)
304-830-1441 (cell)
304-232-5006 (fax)